

11 JUL 1941

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME DIPLOMAT Report N Os. No. 5320

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey ALTERATIONS. When due.....

RETAIN

Subject to four ventilators (removed for deck cargo) being refitted at the first convenient opportunity.

WAG

10.7.41

W382-0002



© 2021

Lloyd's Register
Foundation