

ed by Chief Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

SEL'S NAME "DULWICH" Rpt. Nwg. No. 97637

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


re of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 2

This Survey, due 3,39 now held ~~partly~~ <sup>minor</sup> ~~now~~  
~~completed~~, and the following repairs carried out (due to wear & tear ):-

It is submitted the vessel is eligible to remain as classed, with  
 notation of L.M.C. 7,39 as recommended.

W384-0134

1.8.39



© 2019

 Lloyd's Register  
 Foundation