

[Thin Copy for attaching to Report.]

Lloyd's Register of Shipping.

Port OF HULL.

19th August, 1940.

Sir,

With reference to the
now being held on the Steamer
"RE MOOSE", 6103 tons gross of London,
to inform you that, in consequence of
condition of this vessel's main circulating
pump impellor

it will be my duty to recommend to the Com-
that the same be re-examined
the end of February, 19 41
provided for in the Rules, extracts from
appear on the other side:—the con-
dition of the vessel's character in the
Register Book to be subject to the
fulfilment of this condition.

I am, Dear Sir,

Yours faithfully,

H. Clivis Juniper.

Engineer Surveyor to Lloyd's Register.


1910-0181
W389-0181

Grey, Esq.,

Superintendent Engineer,

Messrs. Runciman, London, Ltd.,

LONDON, E. C. 3.



Lloyd's Register
Foundation

and windlass.

Repairs see continuation sheet