

7 MAR 1940

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME "FRANCES MASSEY"

Rpt. Hul.

No. 50546

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Hull Surveyors report the vessel examined afloat after grounding.

Soundings taken and no leakage found.

The Surveyors, however, recommend the vessel be further examined at the next drydocking.

It is submitted action be deferred accordingly.

INSERT IN S. R. L. Drydocking, grounding.

[Handwritten signature]
7. 3. 40



© 2019

Lloyd's Register
Foundation

W395 0083

Y.M.
if on E
Month
ds. &c.
low asc
if weat
letter
o. of ...
ate if n
h
on bou
length
er
Warp
ad Run