

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 10th February 1917 When handed in at Local Office 14 FEB 1917 Port of NEWCASTLE ON TYNE.No. in Survey held at North Shields Date, First Survey 11th Jan Last Survey 5th July 1917
Reg. Book. (No. of Vessel)20 Lugs on the Wood, Iron or Steel S. K. "Janix" Master E. A. KingTONNAGE:— Built at Selby By whom Cochrane & Sons Ltd When 1916GROSS 425 Owners Humbers Steam Coasters, Ltd Port belonging to HullUNDER DECK ✓ Owners' AddressNET ✓ (if not already recorded in Appendix to Register Book).Surveyed Afloat or in Dry Dock? Afloat Name of Dock Shields Eng. Co Destined Voyage CoastingWB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.Last Report, No. PortCHARACTER.
Date of last Survey and of Periodical Surveys.
100 A.1.
Class Contemplated
Machinery and Boiler Surveys (including date of N.B., if any).In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓REPAIRS, OR EXAMINATION AS PER RULE, FOR 1st EntryNow done:— Vessel placed in Dry Dock, bottom & rudder, cleaned, examined & coated. Top of Engine & boiler casing riveted up & freeboard verified as per Hull letter 1/11/16.

RETAIN

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Stringers	Dblg. Plates under Sounding Pipes	Copper, or T.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Feet.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Openings, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Steering gear and its connections	Transoms	Equipment letter
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Breasthooks & Stemson	Anchor, No. of
Transoms	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" length (on board) size
Reverse Frames		Ditto ditto at other places ditto	" Rule length size
Floors		Stringers, Clamps & Shells ditto	Hawser & Warps
Keelsons		Salting (State if examined.) ditto	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptnD11, &c."

This vessel is eligible in my opinion to have the class contemplated with fresh record of survey 2,17

Survey Fee (per Section 25) ...	£	Fees applied for,	10
Special Damage or Repair Fee (if any) (per Sec. 25) ...	£	Received by me,	19
Travelling Expenses (if chargeable) ...	£		
Second Surveyor's Fee (if any) ...	£		

Committee's Minute

Character Assigned