


of "Laura".

Rot. Rpt 10004.

It is submitted that the Rotterdam Surveyors should be requested to state the number & area of the donkey boiler safety valves, the pressure to which they are adjusted, if they are fitted with easing gear & if steam from the main can enter the donkey boiler. as these particulars are not given on the report forwarded to this office.

201-4/4/16



J.W.D.

3/4/16.

J.W.D.

© 2021

Lloyd's Register
Foundation

W4-0192

W4-0194 1/2

COPY