

M. V. HIDLEFJORD

F.E. Cpn. 7796

It is concluded that the double bottom tanks aft ~~have~~
have been listed as required by the Rules, but the
Surveyor should state if this is so.

SJR

29.9.28



© 2019

Lloyd's Register
Foundation

W 400-00 54