

LIST OF SPARE GEAR SUPPLIED TO THE STEAMER

"HJALMAR BLOMBERG".

- 2 bolts and nuts (or studs & nuts) for each size of rotor bearing  
2 " " " " " " " " " main gear wheel bearing.  
2 " " " " " " " " " pinion bearing.  
1 set of coupling bolts of each size used.  
One-twentieth of total number of bolts and nuts (or studs and nuts  
for each gear case joint.  
One-twentieth of total number of each turbine casing joint.  
2 thermometers for oil circulating system.  
1 set of bearing bushes for slow speed gear wheel shaft.  
1 " " " " " " one high speed gear wheel shaft.  
1 " " " " " " one turbine rotor.  
1 " " " " " " one slow speed pinion shaft.  
1 " " " " " " one high " " " "  
One-half of total number of carbon rings used for turbine glands  
with springs.  
8 pads for one side of main thrust block of Michel type.  
2 thrust bearings for turbines.  
1 set of feed pump valves.  
1 " " bilge pump valves.  
An independent lubricating pump fitted in spare.  
1 escape valve spring of each size fitted.  
A quantity of assorted bolts, studs and nuts , bars and plates  
of iron or mild steel.
- ✓
- 1 propeller.  
1 propeller shaft.  
A number of boiler tubes.  
3 stay tubes.  
1 set of fire bars.



© 2019

Lloyd's Register

W400-0139