

COPY.

J.W.WHITTALL & CO LD.

ISTANBUL

18th April, 1939.

The Secretary  
Lloyd's Register of Shipping,  
LONDON, E.C.3.


Dear Sir,

s.s."HERISLE" and s.s."HERPORT".

In reply to your letter Ref F of the 14th inst.  
we have consulted our Surveyor, Mr. J.L.Campbell, who states  
that the cover plates of the manholes on the bridge deck are  
spaced watertight pitch and that they were properly jointed  
and made watertight.

We presume this is all you require.

Yours &c....



W406-0271

© 2019

Lloyd's Register  
Foundation



25 APR 1939

.....

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

the machine was at the time of the

COPY



© 2019  
Lloyd's Register  
Foundation