

"HERPORT"

EXT FROM IST. (LLOYD'S AGENTS) RPT 8 NO. 3746 (L.A.6097)
dated 4.8.38

The Owners Representative stated that the above requirements
would be carried out at the end of the present voyage when
vessel will be drydocked.

82.B.
26.8.38



© 2019

Lloyd's Register
Foundation

W406-0290