

length on	251.0	Frame Depth 8	Ceiling 20.1	Peak 2237.47	Addition for Keel below base line for draught 1.6 inches
-----------	-------	---------------	--------------	--------------	---

GRAMS—REGISTER, DETROIT

TELEPHONE MAIN 3061

# LLOYD'S REGISTER OF SHIPPING

1121-22 DIME SAVINGS BANK BUILDING

DETROIT, MICH.,

4th December, 1919.

COPY

## PROVISIONAL CERTIFICATE.

This is to certify that the freeboards assigned by the Committee to the steamer "LAKE FAIRPORT", (Detroit Shipbuilding Company's No. 270) have been marked on the vessel's sides and verified by me and a Report has been forwarded to London with a view to the official certificates being issued.

*Wm R. Mitchell*

Surveyor to Lloyd's Register.

from centre of disc to top of statutory deck line-----4ft 3ins.  
fresh water line above centre of disc----- 6 3/4ins.  
Indian Summer line above centre of disc----- 4 1/2ins.  
water line below centre of disc----- 5ins.  
water North Atlantic line below centre of disc----- 7ins.  
top of statutory deck line above iron upper deck at side----- 1 1/2ins.



© 2019

Lloyd's Register  
Foundation

responding percentage  
(Para. 11, 12, 13, or 14)

FREEBOARD recommended amidships from centre of Disc to top of Statutory Deck Line, Wood (Iron) Deck :—

N.A. Winter „ „ „ „



RETAIN

COPY

W. R. M. R. M.

RETAIN



© 2019

Lloyd's Register  
Foundation

1 on  
LINE.

ECTED  
SIONS.

efficient of f  
modification  
Para. 4 (a)  
efficient as

er { Stem..  
{ Sternp

er at  $\frac{1}{2}$  of  
gradual mean  
standard mean

If limited a

Rise in She  
ron amidsh  
Para. 18 (e)

Fall in Sh  
Para. 18 (f)  
length unco

freeboard, T  
correction fo

freeboard b

Difference  
percentage

correction t  
cover  
allowance f

forecastle.

bridge Hou

Raised Q

oop.....

Tota

length of

correspond

(Para. 4

REEBO