

4 E

22 APR 1948

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME "BOCA MAULE"

REPORT

Vpo. No. 2367

ks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH


Main steam pipes tested and electrical installation generally examined.

IT IS SUBMITTED that this vessel is eligible for the Record "Examined 7.47" (8 months).

Yhu

23. 4. 1948 ©. 2019

W 409 + 0066



Lloyd's Register
Foundation