

10th December, 1921.

Dear Sirs,

I beg to inform you that the new steamer "Cocamauk", constructed by Messrs. The Dublin Dockyard Co. Ltd. (Yard No. 114), has left, in tow, for Glasgow, where machinery is to be fitted by Messrs. D. Rowan & Co.

A press copy of Dublin Report No. 4158 on fitting sea connections is enclosed, together with a Board Certificate, in duplicate.

The Electric Lighting Installation is being fitted by Messrs. Telford, Crier & Mackay, Glasgow; part of the wiring has been done and the installation is to be completed at Glasgow, and I should be pleased if you would kindly give the matter your attention; no report has been written.


To complete the Survey on the hull the following aims to be done:-

The riveting of boiler stocks to be completed after the boilers are shipped.

Screen bulkhead to rivet.

Galley sole and beams in way to rivet.

© 2019



Lloyd's Register
Foundation

(2)


Engine Casings top to rivet.
R.C. Deck tested in way of E.T.B. Casings.
Downdraught Pump and hand Pump forward were tested.
Ventilator tube to tunnel recess to be fitted.
Tunnel watertight door to be fitted.

I am, Yours faithfully,
A. G. Lorster.

The Surveyors,
Glasgow.

WATER

W409-0077



© 2019

Lloyd's Register
Foundation

E FOR FEES...

e Room
tion Spaces

Tonnage
Beam ...
H on Deck
Rule ...

us of Ship

1

peaks

way of D

of Frames

"

SED FR

way of D

"

IG, depth

5, depth

at mid

way of E

ickness at

pth at $\frac{3}{4}$ t

ight exte

in Cell

state if

Spacing

GIRDE

"

"

"

Brackets

RDERS

"

"

"

PLATE

ARRIED

EL,

"

Brackets

Leight o

BOTTO

thi

"

Upper

Angl

In way

Spaci

"

Angl

Spaci

ird an

Bulb A

Angles

Spaci

oop D

"

Angles

Spaci

"

Angl

Spaci

recas

"

Angles

Spaci

"

Spaci

(2)

spined R. I. S. p. g. in hatched out. Head D. I.
hatched out known of great heat has great internal
hatching out except current at about 100 fathoms
hatching out each digitized annual

RE

RE

S/S FPG



© 2019

Lloyd's Register
Foundation