

complete the Surveys should be summarised. State clearly the cause of Repairs, if a
extent of Examinations and subsequent repairs. Repairs on account of Damage (if
should be separated from Repairs due to other causes; and besides being detailed in
summarised in the form shown below. Whenever the replacement of Anchors or

[Thin Copy for attaching to Report.]

Lloyd's Register of Shipping.

Port Stull

21.1.41.

Dear Sirs,

With reference to the
survey now being held on the Steamer
"HOLYSTONE"

to inform you that, in consequence of
condition of this vessel's port main
furnaces

it will be my duty to recommend to the Com-
tee that the same be specially examined
before the end of July 1941

as provided for in the Rules, extracts from
which appear on the other side:—the con-
sequence of the vessel's character in the
Society's Register Book to be subject to the
fulfilment of this condition.

I am,

Yours faithfully,

W. S. Shields
Engineer Surveyor to Lloyd's Register.

Northumbrian Shipping Co. Ltd.
Newcastle

Lloyd's Register
Foundation

W41-0136

the Tanks been examined internally

Air and sounding pipes

the Tanks been tested?

Doubling Plates under Sounding Pipes