

11,30.

15 JUL 1940

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "LETICIA". Rpt. Cco. No. 1902.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 1st Special Survey No.3, due 1,40 has been commenced. Repairs to riveting in bunkers were required.

The Curacao Surveyor now reports this tanker placed in dry dock, bottom coated, the Special Survey completed, repairs or renewals effected to deck plating, deckhouses, oil bulkhead; steering arrangements, riveting etc.

It is submitted the vessel appears worthy to remain as classed with record of survey 5,40 and notation S.S.No.3-6,40.

100A1

6,40 Cco.

S.S.Cco.No.3-6,40

"Carrying Pet. in bulk"

"Fitted for oil fuel etc"

f.c.d

10.7.40.

S.R.L:- Delete 'Riveting repairs'

NOTE. THE VESSEL IS REPORTED TO HAVE BEEN SUNK- WAR LOSS.

© 2019

Lloyd's Register
Foundation

W410 0074