

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "LEO" Rpt. HUL No. 50567

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs being effected to bow plating and framing at the first convenient opportunity and to the engine casing top being repaired at the Special Survey.

The 3rd Special Survey No. 1 due 11.37 has been commenced and the year of grace granted.

Some repairs are required to casing top and several plates just above the bilge, port and starboard sides, require to be drilled.

The vessel has been laid up and the usual undertaking was furnished.

With a view to extending the class for a period of 12 months from October last, a partial General Examination was carried out at Hull in November last, ~~and provided the examination be completed and favourably reported upon the desired extension has been agreed to.~~

Repairs are required to bunkers and to main deck plating and framing in way.

A further proposal for an extension of 12 months ^{to date} from the 25th January last has ^{recently} been agreed to provided the requisite repairs ~~can~~ be carried out.

The Hull Surveyors report the vessel afloat and the Special Survey advanced.

The vessel has also been generally examined and repairs effected to casing top, bunkers, framing, a number of hatch covers removed and other repairs carried out. *Defensive equipment has been fitted*

Two new wood deck houses have been erected on the bridge deck.

W410-0138(1/3)

Lloyd's Register
Foundation

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "LEO" Rpt. HUL No. 50567

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Continued.

In the Surveyors' opinion the proposed postponement of the completion of the Special Survey merits approval.

from date of repairs 3.40
It is submitted action be deferred, the extension of 12 months [from January last] granted and a record of **Examined 3.40** be inserted in the Register Book.

28.3.40

S.R.L. Delete repairs to Engine casing top, bunkers, framing and deck plating on way.



© 2019

Lloyd's Register
Foundation

W 40-0138(213)

11.39.

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor

SSEL'S NAME "LEO" Rpt. HUL No. 50567

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Continued.

In the Surveyors' opinion the proposed postponement of the completion of the Special Survey merits approval.

It is submitted action be deferred, ~~and~~ the extension of 12 months from ~~2~~ January last ~~is~~ granted & a record of ~~EXAMINED~~ 3 40 ~~be marked~~ in the Register Book

S.R.L. Delete repairs to engine casing top, bunkers, framing and deck plating in way



© 2019

Lloyd's Register Foundation

W410-0138 (3/3)