

ical Surveys, when held, must be reported in detail and serialim in the terms of the Rules and items remaining to complete Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations subsequent repairs. Repairs on account of Damage (the cause of which

ss Os! - 5,47 (Dr)

2 E

E2 NOV 1948

Chief Engineer Surveyor

Received from Chief Ship Surveyor

S NAME "RO JO"

REPORT

Cpn. No. 12527

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/32.)

COMPLETION OF SPECIAL SURVEY OF ENGINES-AND-BOILERS FOR-S-S--No--

This Survey, due 5.48 ~~now~~ partly held 5.48 now

completed, and the following repairs carried out (due to damage through collision):-

The thrust shaft skimmed up in the lathe and the shoes re-metalled and some other minor repairs effected.

It is submitted the vessel is eligible to remain as classed, with notation of BS 5.48, as recommended.



© 2019

Lloyd's Register Foundation

W412-0061

1. 11. 48.

Efficient	Cement or Asphalt in F.P.	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
part of bow		Oil Bunkers	When fitted, Month