

Chief Ship Surveyor 6. 3.17

Received from Chief Ship Surveyor

NAME Single S.S. "SOUTHWICK". Rpt. Sld. No. 26927

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

It is submitted before this case receives consideration the Sunderland Surveyors should be requested to state whether they are correct in reporting that the spacing of the $\frac{5}{8}$ " rivets in the landing edge of A & B. strakes is $3\frac{1}{14}$ of an inch

They should also be asked to state clearly whether the Boiler Room Bulkhead has been constructed in accordance with the approved plan, or with the amended plan.

Ln 6/3/17


6. 3. 17

$3\frac{1}{14}$ "



© 2019

Lloyd's Register
Foundation

W412-0068