

by the Committee to this vessel, have been correctly marked on the vessel's sides.

3. 1500, 12.27.

MS.

Nº 14361

FREEBOARD REPORT on the

S.S. Southwick

It is submitted the Surveyors be informed that it is observed that the freeboards of the above vessel are given on Middlebury report Nº 14361, dated 28th. Feb. 1931, as 1'-6". As the summer freeboard assigned ~~is~~ 1'-0" it is concluded that the Surveyor was in error in reporting these the 1'-6", but he should conform this.

S.T.B

10/8/31



© 2019

Lloyd's Register  
Foundation

W 412 - 0125

Corresponding Draught

10 ft. 10 ins.