

COPY.

Lloyd's Register of Shipping.



Port OF LIVERPOOL.

12th June, 1947.

This is to Certify that

H.S. NEWTON.

the undersigned Surveyor to this Society did at the request of

the Owners and on behalf of their Underwriters survey the steam trawler "RED GAUNTLET", 410 tons gross of London, whilst lying afloat in Wyre Dock, Fleetwood, on 31st May, 1947, on account of damage stated due to encountering ice on 1st May, 1947, South West of Bear Island.

For further particulars please see Skipper's report (copy attached).

FOUND.

No.1 stem plate in C. & D. strakes set in and corrugated.

RECOMMENDED.

To be removed, faired and refitted.

All new and disturbed work to be painted, and all items renewed for access to be replaced on completion.

These recommendations were made in order to place the vessel in as efficient a condition as she was prior to the damage being sustained.

On account of local conditions it was not possible to effect permanent repairs at this time. Efficient temporary repairs have been effected by testing and making good as necessary all riveting and caulking in way of the damage.

Harry S. Newton
SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register of Shipping

COPY.

Port of LIVERPOOL.

18th June, 1947.



This is to Certify that

the undersigned Surveyor to this Society did at the request of

the Owners and on behalf of their vessel, the steam tug "RED GAUWERT", 410 tons gross, of London, whilst lying afloat in Wyre Dock, Fleetwood, on 18th June, 1947, on account of damage stated due to encountering ice on 18th June, 1947, South West of Bear Island.

For further particulars please see Surveyor's Report (copy attached).

To be removed, fairing and refitted.

No. 1 stem plate in C. & D. strakes set in and corrugated.

All new and disturbed work to be painted, and all items renewed for access to be replaced on completion.

These recommendations were made in order to place the vessel in as efficient a condition as she was prior to the damage being sustained.

On account of local conditions it was not possible to effect permanent repairs at this time. Efficient temporary repairs have been effected by testing and making good as necessary all riveting and caulking in way of the damage.

Surveyor to Lloyd's Register
H. J. 2. 1947

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any statement or any statement contained in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Surveyors or other Officers or Agents of the Society.

Lloyd's Register
Foundation

TON
GROSS
UNDER
NET
Surveyed
Cell D Bo
total cap
N.B.
Last
(Periodical
the Sur
and Jul
other cl
replaced
State al
In dama
off
REPAIR
SUMMAR
Re
Re
Fa
PRESEN
Decks
Caulking
Coaming
Beams &
Outside
Frames
Reverse
Longitud
Transver
Floors
Keelsons
Stringers
Inner B
Have th
Have th
Gen
Th
Rem
No
Survey
Special
Travell