

S.S. "WOLFSBURG"

It is submitted this report might be returned
to the Leith Surveyors, and they should be asked to
correct the report regarding the examination of
double bottom, and under engines and boilers.

ARR *HLL*

8. 5. 19.



© 2019

Lloyd's Register
Foundation

W418 -0 213