

28 JUN 1935

Ans

POST.

INCHES.

ecture


n.12.32.

BOARD REPORT on the Motor ship "Canada"

It is submitted the Copenhagen Surveyors be requested to forward the following information for the purpose of completing their forward report:

1. Are fittings for lashing for securing hatchway covers provided as required by Rule XVI of the Convention?
2. What is the height of the sill of the crew's companionway in the deckhouse aft?
3. Are the ventilator cowings 1470 mm in height specially supported as required by Rule XXIV of the Convention?
4. What is the length of bulwarks on the facing port area provided on each side of the ship abaft the bridge on the forward deck?

Retain plans.



St. B. Loyd's Register

2-7-35 Foundation

W 420-9521

28 H. B. Lyden.

SURVEYOR TO LLOYD'S