

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *SH S* "BRITISH ENDEAVOUR" *Rpt.* *huc* No. *81948*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

1st Long
Transverse No. *10450*

Depth "d" *✓*

Framing: Table No. *✓*

Description

Longitudinal framing

2nd Longitudinal No. *29450*

Proportions Length = *13.82*
Depth =

Deck Sheerstrake

as approved.

Revised Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel). "Carrying Petroleum in Bulk"
2 D^{cs} (Stl). Web frames. Longitudinal framing
Cell DB v E. B 51' + 31' 239t, D.T. 31' 264t, F.P.T. 135t, A.P.T. 69t.
F.K, 16 B.H (11 B.H to upper D^c, 5 B.H. to 2nd D^c). , pt em, Clays A. CP.
P 93', B 30', F 55'. "machy aft"



Lloyd's Register
Foundation

W 421-0182

24.10.27

Lloyd's Register
Foundation