

"BEULAH" REPORT OF TOTAL LOSS, CASUALTY, &C.

Section 2 WRECK DAY No. 161 9462

No. 20898 21337 in R. B. Wreck Book, 115/37 Date of writing this report 20th June, 1938
 Vessel's Name Steel Twin Sc. No. 9 "Beulah" of Parama Tons { Net 1042 Gross 1389
 Built at Ferig When 1923 3 Casualty notice sent to Owner 15/3/38 Owner's reply 30/3/38
 Owner's Name Barrisco, Inc. (Flood Bros, Mgrs.)
 Address 444, Market Street, San Francisco Cal, U.S.A.

RETAIN

SOURCE OF INFORMATION

Case previously before Date 10th May, 1938 Particulars of Classification
 Classing Committee. Last Minute Deferred +100A1 +LMC10,33
 7,37 +LMC(M)6,36
 s.s. No 3-10,33 DBS6,37
 Oil Eng. TSN 7,37 09

Date of Casualty 28th December, 1938

Precis of particulars of Casualty This vessel sank at her moorings at Ogden Point, Victoria, B.C., on the 28th December, 1937, after listing when loaded with a deck cargo, and was raised on the 8th March last.

The Vancouver Surveyor examined her in dry dock and afloat. The bottom and rudder were found good but there were several small indents in the shell plating. The decks, particularly the after deck, were found collapsed and the deck beams distorted, the centre line stanchions buckled, Nos. 2 and 3 hatches distorted, etc.

The poop side boats, bulwarks, masts and rigging damaged and the vessel throughout damaged by submersion.

The case has been submitted to the Committee from time to time and action has been deferred, no decision having been made by the Owners and Underwriters regarding repairs.

Upon inquiry at Lloyd's, it has now been ascertained that the Underwriters have accepted this case as a Constructive Total Loss.

4th January, 1940.

In a letter dated the 4th ultimo, the Vancouver Surveyor states that this vessel has been sold and has been reconditioned.

According to Lloyd's Index she left Vancouver on the 18th ultimo for Singapore.

In accordance with Standing Instructions, the case is submitted to the Committee in order that the present casualty record may be altered to "Sunk in port 12,37 - Refloated and now trading".

Suggested Record X Sunk in port 12,37 - Refloated
 Date of Committee TUE. 21 JUN 1938

Committee's Minute Sunk in port 12,37 - Refloated

W.B. No 161
Section 2



© 2020

Lloyd's Register Foundation

Suggested Record Alter standing record to "Sunk in

part 12-37 - Refloated and now trading"

Date of Committee FRI. 5 JAN 1940

Committee's Minute Sunk in part 12.37

Refloated & now trading.

Write Lloyd's
✓
JC



© 2020

Lloyd's Register
Foundation