

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

1000 OF TRADE BLDG.
MARKET STREET
SAN FRANCISCO, CAL.

ANTWERP
HAMBURG

FLOOD BROTHERS

STEAMSHIP OWNERS


FLOOD LINES, INC.

STEAMSHIP OPERATORS

CABLE ADDRESS
"FLOODBROS"

CODES
SCOTT'S 10TH EDITION
A. B. C. — LIEBERS
BOE — ACME
BENTLEY'S

June 18, 1938



Lloyd's Register of Shipping
71, Fenchurch Street
London, E. C. 3, England

Dear Sirs:

M. S. "Beulah"

In reference to your letter of May 10th referring to the above vessel.

We have been paid a constructive total loss on the M. S. "Beulah", and no doubt the vessel will be sold as is at Victoria.

It is impossible to state at the present time whether the vessel, if purchased by us, will be fixed up according to Lloyd's requirements.

Yours very truly,
FLOOD BROTHERS, INC.
By *RO Flood*

ROF:bg



© 2020

Lloyd's Register
Foundation

W425-0065

W425-0072

Handwritten signature/initials

17238

Referred to Mr. Dyer

Handwritten signatures and initials

28 JUN 1938

100:ps

BA 0507
LLOYD BROTHERS, INC.
LONDON

Dear Sir,
I have the pleasure to inform you that the lease for the premises at 100, Strand, London, which was granted to you by Lloyd Brothers, Inc. on the 1st day of June, 1937, is now being offered for sale by the company. It is your responsibility to advise me of the amount of the bid you wish to make on the 1st day of July, 1938. If you have any questions regarding the lease, please refer to the lease agreement.

Yours faithfully,
W. J. Bennett

W. J. Bennett
Lloyd Brothers, Inc.
100, Strand, London

RECEIVED
LLOYD BROTHERS
27 JUN 1938

1006 19' 7022

LLOYD BROTHERS, INC.

LLOYD BROTHERS



© 2020
Lloyd's Register
Foundation

RECEIVED
LLOYD BROTHERS
27 JUN 1938