

COPY.
COPY.

Register of Shipping,

71, Fenchurch Street, E.C.3.

10th May, 1938.

ENCLOSURE.

VANCOUVER.

4791. "BEULAH" The contents of your report are noted and in the circumstances the Committee have deferred consideration of the case pending repairs and completion of Second Special Survey No.1. I shall be glad to be apprised of any decisions that may be arrived at by the Owners and Underwriters on the subject of the repairs. I enclose herewith a copy of a letter 4790 and 98. "ASTORIA" Owners on the subject of repairs. As recommended, subject to electrical repairs being effected at the first opportunity. I shall be glad to learn the reason for adjusting the safety valves of the Donkey Boiler at a reduced pressure, and whether this was done on account of the condition of the boiler at the Owners' request. Perhaps you will also state at the same time whether the electric cables under the windlass have been repaired as recommended by the Newcastle Surveyors in January last.



© 2020

Lloyd's Register
Foundation

W425-0070

W425-0072