

4 E

6.33

m.7.37.

ived by Chief Engineer Surveyor .....

Received from Chief Engineer Surveyor .....

SEL'S NAME "BEULAH". Rpt. Ver. No. 4791.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(\* The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

The vessel is reported by the Vancouver Surveyors to have sunk at her moorings. An examination has now been made in dry dock. A complete examination of the machinery will be necessary, but no definite arrangements have been made for such an examination.

It is submitted action be deferred.

*[Signature]*  
6.5.38.



© 2020

Lloyd's Register Foundation

W425-0076

nel(s)  
der stea  
ler stea  
ers?  
iler?  
iler?  
at the  
efficient  
after e  
ly lubri  
ring of  
r fitted

Con  
her

ms.

ca

for  
nsequ  
11, 1

4 E

REMAIN



© 2020

Lloyd's Register  
Foundation

(Period  
 occur  
 occur  
 beside  
 dates  
 In dan  
 off  
 Was s  
 Did th  
 If th  
 And w  
 Also w  
 Sur  
 State  
 Did th  
 Did th  
 Did th  
 Did th  
 Has  
 Has  
 Has  
 State  
 If th  
 G  
 Sa