

Lloyd's Register of Shipping

Inches Ship	Inches per Or as	Inches per As
1 5"		
2 5"		
7 2 1/2"		
0"		
10"		

by Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____

EL'S NAME _____ Bucket Dredger "NO. 520" Rpt. Gls. 57064
Rot. No. 24752
Abn. 18732

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey _____

It is submitted the Southampton Surveyors be furnished with particulars of the equipment placed on board at Aberdeen as reported by the Aberdeen Surveyors (Abn.18732); also with the particulars of the equipment as approved and requested to forward at their ^{earliest} convenience full particulars of the equipment on board.

5.7.37

LLR

© 2020
Lloyd's Register
Foundation

Note - Hull Survey completed 10 36

4 anchors at 15 cwts. = 60 cwts.