

1E

y Chief Engineer Surveyor

Received from Chief Engineer

Rpt. 24752

'S NAME

Buckw. Dredger

Rpt.

Aberdeen

No. 18731

86

57064

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Now Propelled

If Boilers fitted with forced draught

no

~~Tail Shaft. If fitted with a continuous liner~~
~~If fitted with an outside gland of~~
~~approved type~~

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ N.B. 10.36

 Filter for O.D. 10.36
 J. Pakin 180 17

Jum

25.5.37



© 2020

 Lloyd's Register
 Foundation

W425-0214