

*Lon* COPY.

C9589

# Lloyd's Register of Shipping.



Port NEWCASTLE ON TYNE.

11th November 1939.

This is to Certify that I have

Surveyed the Steel S.S. "AMBASSADOR", 4450 tons gross, Port of  
Registry Newcastle, as she lay afloat at South Shields on the 9th  
November 1939,

and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report, stating that all repairs  
recommended by me have been completed to my satisfaction, and  
that I have Recommended that she be continued as at present  
classed viz:- @ 100 A.1 with freeboard, 5.39 S.S. Shl. No.3 - 5.37,  
@ L.M.C. M.B. 5.37, B.S. 1.39 C.L. 5.37, and to have fresh record of  
survey,

being fit to carry dry and perishable cargoes.

*John A. Howson*

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register  
Foundation

W 426 - 0198



98292

COPY.

Lloyd's Register of Shipping

NEWCASTLE ON TYNE

Port



11th November 1889

This is to Certify that I have

Surveyed the Steel S.S. "AMBASSADOR", 4480 tons gross, Port of

Registry Newcastle, as she lay afloat at South Shields on the 8th

November 1889.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and

that I have recommended that she be continued as at present

classified viz: - 100 A.1 with freeboard, 8.38 S.S. 2nd. No.3 - 5.37.

at 100 A.1 with freeboard, 8.38 S.S. 2nd. No.3 - 5.37, and to have fresh record of

being fit to carry dry and perishable cargoes.

John W. Dawson

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly carried out, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Surveyors or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register Foundation

NET .....  
Survey  
CellDB  
total ca  
N.B.—  
Last  
(Periodical  
complete  
extent of  
should u  
summar  
should  
respecti  
In damage  
offered  
REPAIRS  
math  
Ca  
New  
SUMMARY  
Renew  
Remo  
Faire  
PRESENT C  
Decks .....  
Caulking of  
Coamings  
Beams & Fas  
Outside Plati  
" "  
Frames .....  
Reverse Fra  
Longitudinal  
Transverses...  
Floors .....  
Keelsons .....  
Stringers.....  
Inner Bottom  
Have the Tar  
Have the Tar  
Gener  
this  
surve  
yp  
as  
Special Dam  
(per A  
Travelling E  
Second Surve