

# REPORT OF TOTAL LOSS, CASUALTY, &c.

No. 13269 in R. B. Wreck Book, p. 65/39

Date of writing this report 16th October, 1939

Vessel's Name *Steel Steamer Trawler "Rudyard Kipling"* of *Fleetwood*Built at *Selby* When *1921* 2 Casualty notice sent to Owner *6/10/39* Owner's reply *11/10/39*Owner's Name *Sum Steam Trawling Co. Ltd.*Address *Wyre Docks, Fleetwood.*

## SOURCE OF INFORMATION.

Previously before  
ing Committee.

Date

Last Minute

## Particulars of Classification.

100 A1	LMC 10,37
Stm Trawler	BS 8,39
SS No 3-6,33	
SS No 1-37	TS 4,39CL

Casualty

16th September, 1939.

Particulars of Casualty This vessel is reported to have been sunk by submarine in the Atlantic on the 16th ultimo.

The Owners concur.

When the Fleetwood trawler Rudyard Kipling (300 tons) was sunk on Saturday, the German submarine commander took the crew of 13 on board and the ship's life-boats in tow. The men were placed in their boats five miles from land. The crew had been on board the submarine for eight hours and they were given food and warm clothing.

Times  
18/9

SEE LIMITATION LIST.

Suggested Record

Date of Committee

Committee's Minute

*Wrecks Lloyd's*

SUNK - WAR LOSS

OCT 17 1939

*Sunk. War Loss*

© 2020

Lloyd's Register  
Foundation