

Mercator

F.E.

Received by Chief Ship Surveyor 2.3.04

Received from Chief Ship Surveyor _____

VESSEL'S NAME S.S. Manchester Mariner Report Spel. No. 12294

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>✓</i>	<i>✓</i>
Spar Sheerstrake . .	<i>2/20"</i>	<i>Proprietary</i>
Description of Framing:— <i>Bulb angle, 1/20" thick, to obtain reduction in foreboard.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\pm 100 A 1$ ("Steel") *"Spar Deck"* as recommended.

$\pm 100 A 1$ ("Steel") *"Spar Deck"*
1 DR (Stc) + Spar DR (Stc) + web frames
W. B = Cell DB = 118' x E x B 44' f 148' 8236 APT 366
FR 684 Cell *Playa* AYCP P30' B92' F34'

C. H. J.
© 2020



Lloyd's Register
Foundation