

3m, 11, 30.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

14 FEB 1940

VESSEL'S NAME "TIBERTON". Rpt. Hul. 50475. No.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

The class is subject to shell plating G3, starboard side in way of fore peak, E.W. 3,38 being specially examined at the next dry docking.

The Hull Surveyors now report the vessel afloat and a bower anchor and 8 lengths of chain cable supplied to replace equipment lost.

Gun stiffening fitted under Admiralty supervision

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as above.

As now, subject etc.



© 2019

Lloyd's Register
Foundation

W433-0055