

1m.12.15.

Yara Kathleen Thurston

F.E.

Received by Chief Ship Surveyor 23.10.18

Received from Chief Ship Surveyor

VESSEL'S NAME

Shells "War Sky"

Rpt. Ss

No. 27361

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 72

Depth "d" 20.87

Framing: Table No. 3

Description

Bulb angle as approved

Longitudinal No. 23832

Proportions

Length = 10.03
Depth =

Bridge Deck Sheerstrake as approved

The Downton pump & keel anchor dispensed with as approved in Standard Vessels

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed


100A-1 (Steel) as recommended.

1 Dk (Steel)

Cell S.B. 276 7346 F.P.T. 1056 A.P.T. 1226

E.K. 7BH. pl. Cam. L.L. 2000 C.P. P. 33 B. 98' F. 28'

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.



© 2019

Lloyd's Register

W435-0083

BEAMS, Second Deck, Single Angle, Bulb)

Angle, Plate, Tee Bulb, or Channel)

Spacing

BEAMS, Third and Fourth Deck, Single Angle,

Deck. Material & thickness

Poop Deck Stringer Plate, breadth & thickness

Angle on ditto