

20 MAY 1942

Im.3.42

sent to Chief Surveyors.....

Received from Chief Surveyors.....


VESSEL'S NAME HEINRICH V. REIDEMANN REPORT Bal No. 7644

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey EQUIPMENT. When due

Subject to the spare bower anchor being tested and 34 fathoms of chain cable being supplied at the first opportunity.



Wals  
20.5.42

Lloyd's Register Foundation

W44-0003

opper, or Y.M. (State if on Folt.) when fitted, Mooth