

Steel S.M.V. "HEINRICH V. RIEDEMANN"

COPY. By whom Bremer Vulkan

Lloyd's Register of Shipping.



Port Baltimore, Maryland

17th February 1942

This is to Certify that I have

Surveyed the S. S. "HEINRICH V. RIEDEMANN"

11020 tons gross of Panama

whilst afloat in the harbour at Baltimore for replacing of one bower anchor
stated to have been lost

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have Recommended that she be continued as classed

* 100 A1 without fresh record of survey subject to 34 fathoms of chain cable
being placed on board at first convenient opportunity

being fit to carry petroleum in bulk.

(Signed) J. G. Buchanan

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register Foundation
W 44-0004

condition, 34 fathom