

before the regulations were introduced requiring a block to be put in the waterline, who

FREEBOARD REPORT on the


S. S. "Gowrie"

This submitted the Surveyor be requested to state if the freeboard marks have now been placed at the middle of the waterline length, and whether clocks have been fitted to take the marks as required by Circular 1248, or if the belting has been cut away in order to render the marking easily visible.

L. 19th

W.D.

19.7.48



© 2021

Lloyd's Register
Foundation

Whit 0-0346

Whit 0-0348

FREEBOARD recommended amidships from centre of Disc to top of Statutory Deck Line, Wood (Iron) Deck:—

0-11"