

COPY.

Lloyd's Register of Shipping,

High Close, Wiltshire Road,
Wokingham, Berks.

11th October, 1939.

Dear Sirs,

H. With reference to the classification in the Society's Register Book of the steamer "ELENA R", I beg to acquaint you that on the occasion of the vessel being under survey in April/May last at Antwerp the Society's Surveyors at that port recommended that some corroded riveting in the side plating should be dealt with before the end of the present month, and in the circumstances I shall be obliged if you will kindly let me know what arrangements are proposed to be made for this matter to receive attention.

I might perhaps add that on the same occasion the Surveyors recommended that some corroded riveting in the keel plating be dealt with at the next drydocking and also that the rudder, repaired by electric welding should then be specially examined.

I am, Dear Sirs,

Yours faithfully,

Clerk to the
Classification Committee.

Messrs Rethymnis & Kulukundis, Ltd.,
Holland House,
1/4, Bury Street,
LONDON. E.C.3.

© 2020

Lloyd's Register
Foundation
W442-0176