

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "ELENA R".

Rpt.

Ant.

No. 22704.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."--Extract from Sub-Committee's Report, 34/5/22.)

Nature of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Boiler Survey, due 6,38, partly held 10,38 now reheld except for the examination of the mountings.

Damage due to frost:- Steering engine cylinder block and the water-end of the general service pump(cracked) renewed.

It is submitted the vessel is eligible to remain as classed with fresh record of survey BS⁵ 39.

The class is subject to the donkey boiler not being used.

It is concluded the Surveyors have assumed themselves of the good condition of the mountings

Yes
Ans. letter
13.6.39
Ymm

Ymm

25.5.39.



© 2020

Lloyd's Register Foundation

W442-0181

