

24 MAY 1935

S.S. "JOYOUS".


This case is stated in endorsement dated 20.5.35, when the Amsterdam Surveyors were asked to state whether, in view of the extensive nature of the damage repairs effected in January last, in their opinion the internal examination of the double bottom tanks could be accepted as part of the 2nd.S.S.No.1.

In reply the Surveyors state that <sup>THE INTERNAL EXAMINATION OF</sup> Nos.1 and 2 double bottom tanks on the starboard side, No. 3 boiler room tank on port and starboard sides, and No. 4 double bottom tank on port and starboard sides could be accepted as part of the Special Survey.

It should be noted that the internal examination of the boiler room tanks has been previously accepted for Special Survey.

It is submitted the Owners be informed accordingly.

24. 5. 35.



© 2020

Lloyd's Register  
Foundation

W443-0029