

14. 5. 35

Received from Chief Surveyors

14 MAY 1935

S/ Joyous

Report

Amo

No.

13355

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

A No. 1

**SURVEY PARTLY HELD.**

(after an early No 3)

3.35

When proposed to be completed

old, &c.,

Submitted the Owners be advised  
in accordance with the letter  
now received from the Amsterdam  
Surveyors.

GLD

14. 5. 35

The Amst Surveyors should state in detail  
which Amst. Engines were examined &  
the specification should be returned  
to the Owners.

14/5/35



© 2020

Lloyd's Register  
Foundation

W443-0040



For Initial please

THE LLOYD'S REGISTER  
OF SHIP OWNERS AND MANAGERS  
LONDON



© 2020

Lloyd's Register  
Foundation