

18 MAY 1935

of Surveyors 30.4.35

Received from Chief Surveyors 30.4.35

NAME *1/2 Jayous* Report *Amo* No. 13355

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

A No. *1* SURVEY PARTLY HELD.
(after an early h.w. 3)
3.35 When proposed to be completed

Survey held, &c.,

It is submitted the Owners be informed that to complete the Survey all the Rule requirements require to be carried out except the examination of the bottom and rudder in dry dock, internal examination and testing of the Boiler Room tank and the examination of Boiler Room tank top and boiler bearers.

[Handwritten initials]
30.4.35

*See Ass't 29/4/35
re machinery
[Signature]*



© 2020

Lloyd's Register Foundation

W443-0048