

the Committee to this vessel, have been correctly marked on the vessel's sides,
accordance with the printed instructions:—

REPORT on the Conventina Freeboards.

Sea Rambler	33621.	S -1/2	W + 1.
-------------	--------	-----------	-----------

Sea Venture	33825	"	"
-------------	-------	---	---

Worked out



© 2020

Lloyd's Register
Foundation

W443-0216

Freeboards compared and found correct by _____ Date 1/11/20

Form for Certificate A