

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Stregate.

Rpt.

Dd

No. 32672

Marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 3.39 ~~partly~~ held ~~at~~ ^{now} completed, and the following repairs carried out (due to wear & tear):-

Some Boiler tubes renewed.
Water end of Ballast pump renewed.
 Superheaters fitted & a connection therewith
 the steam pipes partly renewed. & new liners fitted
 in N.P. cylinder & valve chest.

It is submitted the vessel is eligible to remain as classed, with notation of 2.7.39 Spt. as recommended.

GA 21/7/39



© 2020

Lloyd's Register
Foundation

W443-0233