

**COPY.****Lloyd's Register of Shipping,**

71, Fenchurch Street, E.C. 3.

25th March, 1930.

Dear Sir,

S.

With reference to Liverpool first entry report No.96691 on the steamer "SULTAN STAR", I may say that it is concluded all the watertight bulkheads to the upper deck, and the riveting of the butts of the bridge and forecastle side plating is as required by the Rules, but I shall be glad if you will enquire of the Surveyors and let me know whether this is so.

I shall also be glad to learn the total length and capacity of the double bottom tanks.

I am, Dear Sir,

Yours faithfully,

pro Secretary.

The Secretary,  
LIVERPOOL.



© 2020

Lloyd's Register  
Foundation

W448-0182

to be &amp; dressed in accordance

of the