

COPY.**Lloyd's Register of Shipping,**

71, Fenchurch Street, E.C. 3.

6th March, 1930.

Dear Sirs,

I beg to thank you for your cablegram of the 28th ultimo in regard to the Twin Screw Steamer "SULTAN STAR", and the information contained therein was at once transmitted to the Owners of the vessel.

I may add that information has now been received here that the vessel's port main engine broke down soon after leaving St. Vincent on her return to this country, and that she has been ordered to proceed again to your port.

I therefore await any further particulars you may be able to send in due course. I am, Dear Sirs,
Yours faithfully,

Messrs. Millers & Corys
Cap Verde Islands Ltd.,
Lloyd's Agents,
ST. VINCENT, C.V.I.

pro Secretary.

Decoded cablegram received:-

"SULTAN STAR ARRIVED EXTENSIVELY DAMAGED DOUBLE REDUCTION
"GEARING STARBOARD ENGINE SURVEY HAS BEEN HELD FORWARDING
"TO YOU REPORT WHEN TEMPORARY REPAIRS TO ENGINES EFFECTED
"VESSEL PROCEEDING AT REDUCED SPEED PORT ENGINE BIRKENHEAD
"KEEPING STARBOARD ENGINE IN RESERVE STOP ALL CARGO MAILS
"AND PASSENGERS SAFELY TRANSHIPPED AVELONA STAR SULTAN STAR
"WILL SAIL BIRKENHEAD FRIDAY AFTERNOON".

Lloyd's Register
Foundation

W448-0188