

ALL COMMUNICATIONS TO BE ADDRESSED TO THE COMPANY.

## BLUE STAR LINE (1920) LTD

TELEPHONES:  
 AVENUE 8020 (4 LINES),  
 AVENUE 3404/5 (2 LINES).

TELEGRAMS:  
 "BLUESTARLI, STOCK, LONDON"

CODES:  
 WATKINS 1904 EDIT. BENTLEY'S PHRASE,  
 SCOTTS A.B.C. 5TH EDITION.

PASSENGER OFFICE:  
 3, REGENT STREET,  
 LONDON, S.W. 1.

BRANCH OFFICES:  
 10, WATER STREET, LIVERPOOL,  
 BUENOS AIRES & SANTOS.



*40, St Mary Axe,  
 London.  
 E.C.3.*


IN YOUR REPLY PLEASE EAT/SNC.  
 QUOTE REFERENCE

4th March, 1930.

Secretary,  
 Lloyd's Register of Shipping,  
 71 Fenchurch Street, E.C.3.

Dear Sir,

"SULTAN STAR".



We have to advise receipt of the enclosed message from the above vessel first thing this morning, from which you will note that the port main engine gearing has broken down seriously and we enclose copy of radio sent to the steamer in reply.

As mentioned over the telephone, the "Stuart Star" and "Napier Star" are both in the vicinity, and we have communicated with them and instructed them to get into wireless communication with the "Sultan Star" and render any assistance that may be required.

We will advise you later of any further developments.

Yours faithfully,  
 For BLUE STAR LINE (1920) LTD.

*E. A. Thomson*

Senior Superintendent.



© 2020

Lloyd's Register  
 Foundation

W448-0190

W448-0191



Referred to the Chief Engineer Surveyor.

ad

-5 MAR 1930

Home Carey  
London

Spl ~~Q.R.R.~~

*[Handwritten signature]*

LONDON  
RECEIVED  
- 2 MAR 1930  
LONDON

*[Handwritten signature]*

RECEIVED  
LONDON  
- 2 MAR 1930



© 2020

Lloyd's Register  
Foundation

LINE (1930) LTD

RECEIVED  
LONDON  
- 2 MAR 1930