

Rpt. 12.

Mt. Wood.

19552

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port Malmo, Aina When received in London Office 7. 2. 21

Vessel's Name ex "Lennart"

Official No. 5842 No. in Reg. Book 64207

Port of Registry (For Foreign Vessels) Helsingborg

Iron or Steel Steel State whether Classed by Lloyd's Register yes

Name of Owners O. Björjesson Date of Verification 1/2/21

29650. I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	1	ft.	11	ins.	✓
From centre of disc to top of statutory deck line) at awning or part-awning deck	✓	ft.	✓	ins.	
Fresh Water line above centre of disc			4	ins.	✓
Indian Summer line above centre of disc			2 1/2	ins.	✓
Winter line below centre of disc			2 1/2	ins.	✓
Winter North Atlantic line below centre of disc			6	ins.	✓
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood on iron deck with the vessel's side	} at main, spar or upper ^{upper} dk.		1 1/4	ins.	✓
		} at awning or pt.-awning dk.		✓	ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

2 openings size 4' x 3' have been at this time cut in the bridge front bulkhead and closed with bolted plates secured by nut and screw bolts spaced 7.5 ins. centers which pass through plate and bulkhead plating.

F. R. Palmer, Surveyor.

(To be filled up in London Office.)

Statement No. 19552 Date of Committee's Minute 10.1.08


Particulars for record in Register Book.	} Moulded Depth	18	ft.	3	ins.	
		} Freeboard	1	ft.	11	ins.
			} Corresponding Draught	16	ft.	10

Freeboards compared and found correct by SKM Date 7.2.21

Is fee paid? _____ Form for Certificate A

Instructions _____ Date _____

Certificate written 7.2.21 Noted for posting Posted



© 2019

Lloyd's Register Foundation
W451-0126