

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.

eller dk  
11.31  
02-31

**COPY.**

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

12th August, 1932.

Dear Sirs,

I am in receipt of your memorandum of the 8th instant intimating that you have been informed by the Owners of the steamer "BLYTHMOOR" that this vessel is expected home from Australia in five or six weeks' time when the Boiler Survey will be held, and in reply I have to say that in the circumstances the Committee, who have had the case before them at their meeting today, are agreeable to this arrangement, subject to the inspection in question being then carried out without fail.

I shall be glad if you will inform the Owners accordingly.

I am, Dear Sirs,

Yours faithfully,

pro Secretary.

The Surveyors,  
NEWCASTLE-ON-TYNE.



© 2020

Lloyd's Register  
Foundation

if assigned  
id now verif

lder  
sha

ks of  
ntie

er, or Y.M.  
State if on  
then put on,

, Yards, &  
tion, how as  
ate if we

ment letter

rs, No. of

(State if

length.....  
(on do  
Rule length

er & War

ng and Ru

he Regis  
as class

WHS4-2018

remain as classed & ... survey