

1m, 9, 20.

W454-0123

FREEBOARD REPORT on the

"Konstantinos Hadjipateras"

It is submitted the freeboards given on the accompanying form being those required by the Tables merit approval, the same to be marked on the vessel's sides, inserted in the certificate of classification, and recorded in the Register Book.

The Surveyor should be advised that it is concluded that a butt plate pre-and-after 8"x40 with double angles 3x3x36 is fitted in the No VI hatchway on the foreward deck, as before the alterations, but they should confirm this.

As the depth of the beams in Nos I, II, IV and V hatchways is reported by them as being in each case $3\frac{1}{2}$ " greater than the depths reported for the beams in the Rotterdam CII report No 21752 of December 1932, they should state if the depths as now reported are ^{those} from the underside of the covers, or from the top of the web plates projecting above the top of the mounting angles. If the latter they should report the depth from the underside of covers.

The foreward certificate copy should be forwarded for issue when the foreward have been marked verified, and the new gross tonnage has been inserted thereon particulars being sent to this office.

It is suggested the foreward foreward survey be carried out at this time.

2-9-37

26 Rot
Dwen
2 SEP 1937

Greek.

Lloyd's Register
S.T. Foundation